



“The lid on my Brabantia Newlcon Pedal Bin has come off”



More often than not, when a lid on a Brabantia Newlcon bin falls off, it is because the capacity tag has broken or fallen off some how.



Capacity tag

If you have a broken or lost capacity tag, please email or call Sheldon & Hammond and we can arrange to send you a replacement under warranty.

warranty@sheldonandhammond.com.au or 1800 808 971